

Chapter 18
Route window W9
Southall west sidings



18 Route window W9 Southall west sidings



Introduction

- No Crossrail works will take place in this route window, other than some minor re-signalling. There will therefore be no impacts related to construction activity, nor any permanent impacts related to issues of land-take or physical change.
- 18.2 The drawings provided at the end of this chapter present the main features of the route window.

The permanent works


18.3 The minor re-signalling works in this route window will not give rise to any significant temporary impacts. The majority of works will be undertaken from within the railway boundary.

Mitigation and temporary impacts

18.4 There are no significant traffic and transport impacts to report in this route window, so no mitigation is required.

Mitigation and permanent impacts

18.5 There are no permanent impacts in this route window.



Crossrail

TRANSPORT AND ACCESS

COPYRIGHT AND MAY LEAD TO PROSECUTION OR CIVIL PROCEEDINGS. (GLA - 100032379) (2005).

SCALE: 1:5000 @ A3 1E0323-W1E00-E00-F-00009